




NEW LIFE
TRANSPORT PARTS CENTER

NEW @ NEW LIFE:

CORNER REPAIR KIT

Corner Repair
For 3/4" thick
ply-metal doors.
3/4"x18"x18"



Part No.
1013875

Replacement Corners:

- Greatly reduces trailer down-time.
- Less costly than complete door replacement.
- Helps keep cargo dry and reduces claims.
- High density foam is impervious to moisture.
- Tested and proven.

Bring "New Life" to your Transport Equipment!

GRAND RAPIDS OFFICE

400 Gordon Ind. Ct. S.W. Byron Center, MI 49315

1-800-748-0555

(616) 878-3633

FAX: 1-800-530-9666

www.newlifeparts.com